


- |                                    |                                   |                                   |   |   |   |   |   |
|------------------------------------|-----------------------------------|-----------------------------------|---|---|---|---|---|
| <p>10</p> <p>36 x<br/>C1-09900</p> | <p>11</p> <p>9 x<br/>K1-01261</p> | <p>12</p> <p>4 x<br/>C1-09910</p> | <p>20</p> <p>9 x<br/>R1-63050<br/>M6x50</p> | <p>21</p> <p>9 x<br/>R3-91246<br/>Ø15x9x15 - M6</p> | <p>22</p> <p>110 x<br/>R1-63221<br/>Ø4x20</p> | <p>23</p> <p>9 x<br/>R3-91360<br/>Ø5x25</p> | <p>24</p> <p>9 x<br/>K3-06039<br/>Ø4,5x40</p> |
|------------------------------------|-----------------------------------|-----------------------------------|---|---|---|---|---|



- |   |   |  |
|---|---|--|
| <p>25</p> <p>4 x<br/>R3-91290<br/>Ø12</p> | <p>26</p> <p>4 x<br/>R3-91060<br/>Ø8x60</p> | <p>27</p> <p>48 x<br/>R1-63470<br/>Ø7x70</p> |
|---|---|--|

